

575 Mountain Avenue Murray Hill New Jersey 07974 Telephone: 201-464-8100 TWX: 710-984-7970

# **MATERIAL SAFETY** DATA SHEET

#262

Walding Consumables and Related Products Conforms to OSHA 1910.1200

#### IDENTIFICATION

PRODUCT NAME: Liquified Petroleum Gas

w/Motyl Acetylene-Propadiene

CHEMICAL FAMILY: Gas Mixture

SYNONYMS: MAPP Gas, Metyl Acetylene-

Propadiena Mixture

DOT HAZARD CLASS: Planmable Gas

CAS NUMBER: None

FORMULA: C3H4 + Alkane + Alkene Hydrocarbons

DOT IDENTIFICATION NUMBER: UN 1075

CHENTREC: 800-424-9300

## HEALTH HAZARD DATA

HAZARDOUS INGREDIENTS	CAS	WT X	TLV (ACCIH)	PEL (OSHA)
Methyl Acetylene-Propadiene	74-99-7	44	1000 ррш	1000 ppm
Liquified Petroleum Gas	None	56	1000 ррж	1000 ppm

# SYMPTOMS OF EXPOSURE:

A Central Nervous System Depressant and Irritant. Inhalation of low concentrations will cause excitement, disorientation. Contact with liquid will cause frostbite, irritation or blindness. Being a simple asphyxiant, inhalation at high concentrations, so as to exclude an adequate supply of oxygen to the lungs will cause unconsciousness, and possibly death.

## TOXICOLOGICAL PROPERTIES:

Repeated exposures to tolerable levels has not shown delerious effects. The major property is the exclusion of an adequate supply of oxygen to the lungs.

DATE OF ISSUE 11-1-86

#### REACTIVITY DATA

#### Stability: Stable

#

Incompatibility (Materials to Avoid): Matural rubber, copper alloys above 65% copper, silver, mercury, halogens, acids, metallic sodium potassium, potassium permanganate.

Hazardous Decomposition Products: None

Hazardous Polymerization: Will not occur

Conditions to Avoid: None:

#### SPILL OR LEAK PROCEDURES

#### STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Evacuate all personnel from affected area. Use appropriate protective equipment. If leak is in user's equipment, be certain to purge piping with an inert gas prior to attempting repairs. If leak is in container or container valve, contact the closest supplier location.

#### WARNING:

Any leaks of MAPP present great danger of explosion or fire. Keep all sources of ignition away.

# Waste Disposal Method:

Do not attempt to dispose of waste or unused quantities. Return in the shipping container properly labeled, with valve protection cap in place to supplier for proper disposal.

# SPECIAL PROTECTION INFORMATION

Leather gloves and aprons when welding, cutting, or brazing. Safety glasses with filter lanses, shade #4 or darker.

Respiratory protection is not normally required. Do not enter area of high MAPP concentration until first purging with inert gas and then ventilating with eir.

Local exhaust - Provide local exhause or mechanical ventilation if welding or cutting in confined areas. Use air supplied respirator for extreme confined areas where TLV's may be exceeded when welding, cutting, or brazing.

## SPECIAL PRECAUTIONS

## Special Labeling Information:

DOT Shipping Name: Liquified Petroleum Gas/Hathyl Acetylene-Propadiene

DOT Shipping Label: Flammable gas DOT Hazard Class: Flammable gas I.D. No.: UN 1075